

**This Page Is Inserted by IFW Operations
and is not a part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




Fig. 1

Transducer	Parameter	4*(1-3) 100 Ω
Backing:	Z(MRayl)	2
Metal towards backing:	Z (MRayl) c (m/s) l (μ m)	30 3750 15
Elem. a:	Lsa(μ H) Cca(pF) Rlsa(Ω) Z ^D (MRayl) c (m/s) h (10 ⁹ V/m) e _r ^s l (μ m) Area (mm ²)	6 100 100 14.06 3569 1.626 888 140 3.0 (2 stk.)
Metal between sub-elements:	Z (MRayl) c (m/s) l (μ m)	20 3750 15 (3 stk.)
Elem. b:	Lsb(μ H) Ccb(pF) Rlsb(Ω) Z ^D (MRayl) c (m/s) h (10 ⁹ V/m) e _r ^s l (μ m) Area (mm ²)	16 100 100 14.06 3569 1.626 888 116 3.0 (2 stk.)
Metal towards front:	Z (MRayl) c (m/s) l (μ m)	30 3750 15
Transf. 1:	Z(MRayl) l/ λ v/2.5MHz	8.04 0.25
Transf. 2:	Z(MRayl) l/ λ v/2.5MHz	2.63 0.25

Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7: Received first harmonic signal from the pressure in Fig. 5, when using the response B11 in reception.









Fig. 8

20250404 14:03:03







ARRAY CONFIGURATION WITH ELEMENT VARIABLE FILTERING

Fig. 13